

Operation at low VIV angles

- Another fan manufacturer's Impeller Failure

